



# United States Antarctic Program

## Palmer Pier Above Waterline Structural Survey RPSC & NSF

2/10/2009

**Raytheon**  
Polar Services




## Overview

---

- Pier thickness measurements
  - Thickness measurements were taken with NIST calibrated ultrasonic metal thickness meter over regular interval along pier above the low tide line
- Pier condition/Photos
- Survey Summary (above and below water)
- Results
- Key Observations
- Recommendations




# Pier Plan





# Areas Surveyed







# Tears in Piles







# Weakened Piles







# Corrosion







# Corrosion and Holes








# More Corrosion

0.1" thick in places








# Growing Holes








# Flaking



Flaking of Sheet Piles. (Enough flaking to show on top of seasonal snows)



# Underwater Corrosion




Worse corrosion underneath water





## Pier Foundation

- Per original 1967 design, bottom of sheet piles were to be placed within trench for pier stability.
- Trench was either not done, or has since eroded around pier near shore




Bottom of Sheet Pile exposed.  
Resting on uneven rock surface



# Unsecure Moorings

1. Moorings pulling out
2. Out of plumb
3. As LMG is moored, tension on the moorings causes them to rise and fall as well as rock in place.







# Unsecure Moorings





# Sink Hole




Largest Sink Hole to date appeared as LMG left Palmer 10/24/2008

- 14” in diameter with undercut edges
- 6 feet deep






# Sink Holes



New Sink Hole  
11/4/2008



# Sink Hole Locations







# Pier Lean


Vertical reference



Pier Wall 5 degrees off plumb



# Pier Bottom




Corroded and broken knuckle





# Hole in Pier



Holes in Pier



# Holes and Thin Areas

---








## Cobbled Area



Very Thin in Cobbled areas and are too uneven to get accurate measurements.




# Large Hole







# Joint Repair





# Hole Repair



Patched Hole with Anode





# Hole Repair



New Patches  
beginning to corrode



# Hole and Joint Repair



Repair of Hole and failing joint





# Above Water Measurements

Average Reductions in Pier Thickness  
(original sheet pile thickness: 0.375”)


|                      | Above Water Measurements |             | Measurements Between High and Low Tide |             | Measurements Above High Tide Line |             |
|----------------------|--------------------------|-------------|--|-------------|-----------------------------------|-------------|
|                      | Average Thickness (in.)  | % Reduction | Average Thickness (in.)                | % Reduction | Average Thickness (in.)           | % Reduction |
| <b>Cell II</b>       | 0.284                    | 24%         | 0.262                                  | 30%         | 0.303                             | 19%         |
| <b>Cell III</b>      | 0.310                    | 17%         | 0.299                                  | 20%         | N/A                               | N/A         |
| <b>Section A</b>     | 0.295                    | 21%         | 0.272                                  | 27%         | 0.308                             | 18%         |
| <b>Complete Pier</b> | 0.296                    | 21%         | 0.278                                  | 26%         | 0.306                             | 19%         |



# Underwater Measurements

Average Reductions in Pier Thickness  
(original sheet pile thickness: 0.375")

|                      | All Measurements Taken (Above and Below Water) |             | Underwater Measurements |             | Underwater Measurements Minus Repaired Sections |             |
|----------------------|--|-------------|-------------------------|-------------|---|-------------|
|                      | Average Thickness (in.)                        | % Reduction | Average Thickness (in.) | % Reduction | Average Thickness (in.)                         | % Reduction |
| <b>Cell II</b>       | 0.341  | 9%          | 0.372                   | 1%          | 0.357   | 5%          |
| <b>Cell III</b>      | 0.376  | 0%          | 0.382                   | -2%         | N/A   | N/A         |
| <b>Section A</b>     | 0.349  | 7%          | 0.385                   | -3%         | N/A   | N/A         |
| <b>Complete Pier</b> | 0.355  | 5%          | 0.380                   | -1%         | N/A   | N/A         |



Negative indicates an increase in thickness (most likely inaccurate)  
We had to use a different probe for the underwater measurements





## Results

---

- 5% overall reduction in sheet pile thickness
- 26% reduction in sheet pile thickness between low and high tide
- 1% increase in sheet pile thickness below water (high probability of inaccurate measurements)
- Severe corrosion mostly concentrated between tide lines
- Local minimums of 0.1" in spots of worst corrosion but still absent of holes



## Observations

---

- Many holes due to corrosion present in piles throughout
  - Cell II has seen the most corrosion
- Walls along mooring edge of pier 5 degrees out of plumb
  - Tilted toward Station, most likely as a result of the ship's pressure on the pier
- Large sink holes forming over Cell II and Section A of pier
- Large holes in Pier above and below water ~10 inches
  - Wave action may contribute to loss of fill behind these holes creating voids
- Areas of significant corrosion resulting in uneven surface (unable to measure thickness with ultrasonic sensor)





## Divers' Comments

---

- Underwater probe's sensor area too large for accurate readings (unable to get solid interface with pier surface in areas of heavy corrosion)
- Underwater probe measured adequate thickness regularly in areas of obvious corrosion and reduced thickness (i.e. inaccurate underwater measurements)



## Repairs

---

- Divers identified 17 areas needing immediate attention
- 6 of these areas were repaired
- 11 areas remain
- Data from survey indicated 21 areas of severe corrosion (holes/weak areas needing repair)
- 15 of these areas were repaired
- Installed zinc anodes for corrosion protection
- The remaining 6 areas to be repaired next season





## Recommendations

---

- Further measurements should be taken with new probe during next year's inspection
- Additional areas of corrosion need to be repaired
- Mooring procedure has been changed to reduce pressure against pier
- Use pier for two years with annual inspection program